

TEST REPORT

Number : TWNH00066233

Date : Oct 18, 2017

Applicant: Soung Pieng Enterprise Co., Ltd.
No. 5, Lane 166, Chongyang Rd.,
Nangang District, Taipei City 115,
Taiwan, R.O.C.

Sample Description:

One (1) group of submitted sample said to be :

Item name : ABS Locker
Item no. : AHL-S
(A)Top Board(B)Back Board(C)Side Board(D)Door Board
Country of origin : Taiwan
Quantity : 1 Piece
Date Sample Received : Sep 22, 2017
Date Test Started : Sep 25, 2017

Test Conducted:


As requested by the applicant, for details please refer to attached pages.

Remark:

Results were transferred from report No.TWNH00065901 dated Sep 30, 2017.

Authorized by:

On Behalf of Intertek Testing Services
Taiwan Limited



Matt Wang
Sr. Manager



TEST REPORT

Number : TWNH00066233

Test Conducted

Formaldehyde content

With reference to CNS 1349(2014/10/02) - Plywood and analyzed by UV-Vis Spectrophotometer.

<u>Tested sample</u>	<u>Result (mg/L)</u>
(1)	ND
(2)	ND
(3)	ND
(4)	ND

Remarks : CNS = Chinese National Standard
mg/L = Milligram per liter
Detection limit = 0.15 mg/L
During the test, the minimum number of specimens that can achieve a total area of 1800cm² is used.



Tested Components:

- (1) Grey plastic (A)
 - (2) Grey plastic (B)
 - (3) Grey plastic (C)
 - (4) Blue plastic (D)
-



TEST REPORT

Number : TWNH00066233



End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: <http://www.intertek-twn.com/terms/>. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.



Page 3 of 3

